

Hastings Deering



ANTHONY PAANS

Default Site

0001 HYDRAULIC SYSTEM

UNIT INFORMATION

M/M - CASE MAGNUM TRACTOR

S/N : ZDRD07124

LOC : AR Gatton

COMPONENT INFORMATION

Make

Mode

W/S

SHOP JOB SEGMENT

001



Condition Monitoring Centre

i Express Post Satchels can be recycled. Please return any unused satchels.

B CORRECTIVE ACTION MAY BE REQUIRED

DATE _____

18/03/2024

LCN

20015915

Viscosity acceptable for oil grade indicated. Medium amount of non-metallic foreign material and magnetic metal was observed. PQ index (Ferrous debris) is high. Iron is slightly high. All other completed test results appear acceptable. **Suggested Action:** Advise further monitoring of this compartment. Inspect the used oil filters for abnormal debris. Review sampling procedure in the event sampling technique has influenced results. More samples are needed to establish a trend. Resample at half the recommended interval to confirm normal conditions. Sample Notes:

CURRENT SAMPLE

TOOK 4 DAYS TO REACH LAB

INTERPRETED BY

Calvin Wang

ANALYSED BY

sarinlines

MAINTENANCE

DATE _____

LCN

PREVIOUS SAMPLE

TOOK 9 DAYS TO REACH LAB

INTERPRETED BY

ANALYSED BY

MAINTENANCE

[illegible][illegible]