



Tractors

LOT 1

Date: 17/02/2025

Location: Merredin

Machine Type: 4WD Tractor

Make: John Deere

Model: 9R640

Hours: 1421

Serial Number: 1RW9640DENA075122

Auto Steer: Starefire 6000

Clean: Yes/**No**

Transmission: E18 Powershift

Engine Oil Analysis: Yes/**No**

Hydraulic Oil Analysis: Yes/**No**

Coolant Analysis: Yes/**No**

Diff/Planetary/Main Gearbox: Yes/**No**

Visual Inspection

| Item | OK | Not Ok | Comments |
|-----------------------|-------------------------------------|--------|------------------------|
| Engine Oil | <input checked="" type="checkbox"/> | | |
| Engine Temperature | <input checked="" type="checkbox"/> | | Infrared Thermal Test: |
| Last Service | <input checked="" type="checkbox"/> | | 8/4/24 900hrs |
| Leaks | <input checked="" type="checkbox"/> | | |
| Filters | <input checked="" type="checkbox"/> | | |
| Air Cleaner | <input checked="" type="checkbox"/> | | |
| Turbo/Exhaust | <input checked="" type="checkbox"/> | | |
| Wiring/Alternator | <input checked="" type="checkbox"/> | | |
| Belts/Hoses/Clamps | <input checked="" type="checkbox"/> | | |
| Radiator | <input checked="" type="checkbox"/> | | |
| Oil Coolers | <input checked="" type="checkbox"/> | | |
| Screen | <input checked="" type="checkbox"/> | | |
| Fuel Pump | <input checked="" type="checkbox"/> | | |
| Fuel Injectors | <input checked="" type="checkbox"/> | | |
| Fuel Tank | <input checked="" type="checkbox"/> | | |
| Batteries | <input checked="" type="checkbox"/> | | |
| Corrosion | <input checked="" type="checkbox"/> | | |
| Covers/Guards | <input checked="" type="checkbox"/> | | |
| Front Planetary Seals | | | |
| Rear Axle Seals | <input checked="" type="checkbox"/> | | |
| Front Diff | <input checked="" type="checkbox"/> | | |
| Rear Diff | <input checked="" type="checkbox"/> | | |
| Drive Shafts | <input checked="" type="checkbox"/> | | |
| Suspension | <input checked="" type="checkbox"/> | | |
| | | | |



| | |
|-----------------------|--|
| Recent Repairs | |
|-----------------------|--|

Transmission & Hydraulics

| | | | |
|---------------------|-------------------------------------|--|-----|
| Oil Level | <input checked="" type="checkbox"/> | | |
| Transmission | <input checked="" type="checkbox"/> | | |
| Powershift | <input checked="" type="checkbox"/> | | |
| IVT/CVT | | | N/A |
| Hyd Pumps | <input checked="" type="checkbox"/> | | |
| Hyd Cylinders | <input checked="" type="checkbox"/> | | |
| Valve Blocks | <input checked="" type="checkbox"/> | | |
| Steering | <input checked="" type="checkbox"/> | | |
| Remote Couplings | <input checked="" type="checkbox"/> | | |
| Leaks | <input checked="" type="checkbox"/> | | |
| Three Point Linkage | <input checked="" type="checkbox"/> | | |

Cab, Electrical and Tyres

| | | | |
|-----------------------------------|-------------------------------------|--|---------------------------|
| Cab | | | |
| Air Conditioner | <input checked="" type="checkbox"/> | | |
| Radio | <input checked="" type="checkbox"/> | | |
| Two-way Radio | <input checked="" type="checkbox"/> | | |
| Windows | <input checked="" type="checkbox"/> | | |
| Upholstery | <input checked="" type="checkbox"/> | | |
| Seat Condition/Function | <input checked="" type="checkbox"/> | | |
| Switches | <input checked="" type="checkbox"/> | | |
| Function Controls | <input checked="" type="checkbox"/> | | |
| Lights | <input checked="" type="checkbox"/> | | |
| Screens | <input checked="" type="checkbox"/> | | |
| Monitors | <input checked="" type="checkbox"/> | | |
| Mounting Points | <input checked="" type="checkbox"/> | | |
| Overall Condition And Comments | | | |
| Tyres | | | |
| Tyre Size | | | 800/55/R46 |
| Duals | | | Front inside dual is flat |
| Wheel Condition | <input checked="" type="checkbox"/> | | |



| | | | |
|---------------------|-------------------------------------|--|---|
| Tyre Condition | <input checked="" type="checkbox"/> | | |
| Tread Depth | | | Front 50mm Rear 50mm |
| Tracks | | | |
| Track Condition | | | |
| Tread Depth | | | |
| Drive Lugs | | | |
| Alignment | | | |
| Idler Condition | | | |
| Tensioner Condition | | | |
| Overall Comments | | | Excellent Condition Machine will need cleaning before crossing state borders |

